

# CIBSE Recommended Light Levels

<b>DISTRIBUTION &amp; STORAGE</b>	
Warehouse/Bulk Stores	100 Lux
Loading Bays	150 Lux
Unpacking & Sorting	200 Lux
Large Item Stores	100 Lux
Packing & Dispatch	300 Lux
Small Item Stores	200 Lux
Cold Stores	300 Lux
Trade Counter	500 Lux
<b>RETAIL</b>	
Small Retail Outlets	500 Lux
Garden Centres	500 Lux
Supermarkets	750 Lux
DIY Superstore	1000 Lux
Hypermarkets	1000 Lux
Showrooms	500 – 750 Lux
<b>OFFICES</b>	
General	500 Lux
Computer Work Stations	300 - 500 Lux
<b>GENERAL</b>	
Entrance Halls & Lobbies	200 Lux
Changing Rooms & Toilets	100 Lux
Corridors & Stairs	100 Lux
Entrances/Exits	200 Lux
Restaurants & Canteens	200 Lux